






Eyewear Inspection Job Aid



Eyewear Inspection Checklist

Confirm Order Was Completed As Requested

- Verify Style (Frame and Lens)
- Verify Additional Services Match Order (Tints/Add Ons/Coatings)
- Verify Safety Requirements (If Applicable)

Lens Fit

- Verify Lens Sizing
- Verify Lens /Bifocal Symmetry

Optical Inspection

- Verify Power/Axis/Add
- Check OC Height/Vertical Imbalance
- Verify PD (Far/Near) Horizontal Prism
- Verify Bifocal Seg Height/Fitting Height
- Verify Lens Thickness


Visual Lens Inspection (Cosmetic Paddle Standard)

- Check Lenses (Scratches/Pits/Chips/Crazing)


Customer Pick Up Ready

- Check Frame Alignment
- Clean Frame and Lens
- Place In Vendor Case

Cosmetic Zone Chart



Cosmetic Zone Instructions	
Zone 1	* Maximum of 1 Defect allowed
	* Less than or equal to 10 on the Cosmetic paddle, both Spec & Scratch
Zone 2	* Maximum of 2 Defects allowed
	* Less than or equal to 20 on the Cosmetic paddle, both Spec & Scratch
	Maximum of 3 Defects allowed per lens, regardless of Zone combinations



Seg Height and Alignment Chart

